



CERTIFICATE OF ACCREDITATION

In terms of section 22(2)(b) of the Accreditation for Conformity Assessment, Calibration and Good Laboratory Practice Act, 2006 (Act 19 of 2006), read with sections 23(1), (2) and (3) of the said Act, I hereby certify that:-

EAST CAPE X-RAY CC
Co. Reg. No.: 1995/046552/23
PORT ELIZABETH

Facility Accreditation Number: **XRAY0011**

is a South African National Accreditation System accredited Inspection Body to undertake **TYPE C** inspection provided that all SANAS conditions and requirements are complied with

This certificate is valid as per the scope as stated in the accompanying schedule of accreditation, Annexure "A", bearing the above accreditation number for

THE INSPECTION OF DIAGNOSTIC X-RAY IMAGING SYSTEMS

The facility is accredited in accordance with the recognised International Standard

ISO/IEC 17020:2012

The accreditation demonstrates technical competency for a defined scope and the operation of a management system

While this certificate remains valid, the Accredited Facility named above is authorised to use the relevant SANAS accreditation symbol to issue facility reports and/or certificates


Mr R Josias
Chief Executive Officer

Effective Date: 07 December 2010
Certificate Expires: 06 December 2014


This certificate does not, on its own confer authority to act as an Approved Inspection Authority as contemplated in the Hazardous Substances Regulations. Approval to inspect within the regulatory domain is granted by the Department of Health

ANNEXURE A

SCHEDULE OF ACCREDITATION

Facility Number: XRAY0011

TYPE C

Permanent Address: East Cape X-Ray CC 67 Mangold Street Newton Park Port Elizabeth 6045		Postal Address: P O Box 34847 Newton Park Port Elizabeth 6055
Tel: (041) 365-3208 Fax: (041) 365-5078 E-mail: eastcapexray@webafrika.org.za		Issue No.: 05 Date of issue: 17 October 2013 Expiry date: 06 December 2014
Nominated Representative: Ms T Tapson	Technical Manager: Mr B Tapson Mr G Keulder	Technical Signatories: Mr B Tapson (3, 4, 5, 6 & 7) Mr G Keulder (3, 4, 5, 6 & 7) Mr C Geswind (3, 4, 5, 6 & 7) Mr C Moore (3, 4, 5, 6 & 7) Mr GJ Perks (3, 4, 5, 6 & 7) Mr LM Els (3, 4, 5, 6 & 7) Mr RD Elshove (3, 4, 5, 6 & 7) Mr AM Weber (3, 4, 5, 6 & 7) Mr RMA Bowler (3, 4, 5, 6 & 7)
Field of Inspection	Service Rendered	Codes and Regulations
Regulatory: The supply of services as an Inspection Body for the Inspection and Test of Diagnostic X-Ray Imaging Systems as defined in the Department of Health's Licence conditions for Diagnostic X-Ray Imaging System. Hazardous Substances Act No: 15 of 1973 as Amended	Functional test and verification of the following: 3. X-Ray Tubes and Generators – Conventional film systems; (tests 1, 4-8, 33-35, 75-89, 115-118.1) 4. Computerised Radiography Reader (tests 18-19, 23, 29-35, 90-101, 119-122) 5. Direct Digital Radiography System (tests 1, 4-8, 24-25, 27, 29-35, 75-84, 102-114, 119-122) 6.1 Fixed Fluoroscopy Equipment (tests 1, 38-42, 75, 79-84, 123-139.1) 6.2 Mobile Fluoroscopy Equipment (tests 1, 39, 79-84, 123-131, 137-139.1) 7. Computed Tomography (tests 46-49, 75, 119-122, 140-146)	Inspection methods and procedures as per Inspection Body's field of activity 1 Ref 19 2 Ref 14 3 IPEM 91, BIR & Ref 18 4 IPEM 91 & KCARE 10.2 (1) – (4) 5. IPEM 91 & KCARE 10.4 (1) – (2) 6. IPEM 91, BIR & Ref 20 7. IPEM 91, BIR & IMPACT

Original date of accreditation: 07 December 2010

Page 1 of 1

ISSUED BY THE SOUTH AFRICAN NATIONAL ACCREDITATION SYSTEM


Field Manager